

X-SKEL MOUNTS - WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes ½" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH
- Manufacturer: WARNE MFG. COMPANY
- Product no.: 947000377
- Mfr. No.: XSKEL1DE
- Elevation: -
- Finish: Dark Earth
- Height: -
- Scope Tube Diameter: 1"
- Style: Competition,3-Gun
- Delivery weight: 0.227kg
- UPC: 656813104802

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: XSKEL MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH \(1.435"\) 0 MOA MOUNT, DARK EARTH Safety Instruction Guide](#)
- [Český: XSKEL MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH \(1.435"\) 0 MOA MOUNT, DARK EARTH Bezpečnostní pokyny](#)

XSKEL MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH Safety Instruction Guide

Introduction

Thank you for choosing the XSKEL Mount by Warne MFG. Company. This guide provides essential safety information to ensure the safe and effective use of your mount. Please read this guide carefully before installation and use.

General Safety Guidelines

- Ensure that the mount is compatible with your scope and firearm before installation.
- Always handle firearms with care and follow all safety protocols.
- Keep the mount and all related components out of reach of children and unauthorized users.
- Inspect the mount regularly for signs of wear or damage.
- Report any unsafe conditions or incidents to the appropriate authorities.
- Stay informed about product recalls and safety updates via the EU Safety Gate platform.

Specific Safety Precautions for Use

- Use the mount only as intended. Do not modify or alter it in any way.
- Ensure that all screws and fasteners are tightened to the recommended torque specifications.
- Avoid using the mount in extreme conditions that may compromise its integrity.
- Do not exceed the weight limit specified by the manufacturer.
- Always check the stability of your setup before use to prevent accidents.

Instructions for Installation and Usage

1. Preparation

- Gather all necessary tools: 1/2" tactical nut attachment and a torque wrench.
- Ensure that your firearm is unloaded and pointed in a safe direction.

2. Installation Steps

- Position the mount on the desired location on the firearm's rail.
- Align the scope in the mount to ensure proper eye relief.
- Secure the mount using the provided #8 Torx style fasteners.
- Tighten the fasteners to 65 in/lb. of torque for a secure fit.
- Doublecheck that all components are securely fastened before use.

3. Usage Guidelines

- Always ensure that your optic is properly mounted and adjusted before firing.
- Regularly check the mount for stability and tightness, especially after extensive use.
- If you notice any signs of damage or instability, discontinue use immediately and consult a professional.

Disposal Instructions

- Dispose of the mount in accordance with local regulations.
- Ensure that any electronic components, if applicable, are disposed of at a designated electronic waste facility.
- Do not dispose of the mount in regular household waste.

Contact Information for Further Support

For any questions or concerns regarding the XSKEL Mount, please refer to the manufacturer's website or customer service for assistance.

By following these guidelines, you can ensure the safe and effective use of your XSKEL Mount. Thank you for your attention to safety.

XSKEL MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH

Bezpečnostní pokyny

Úvod

Děkujeme, že jste si vybrali montáž XSKEL od společnosti Warne MFG. Tento průvodce poskytuje důležité informace o bezpečnosti, aby byla zajištěna bezpečná a efektivní používání vaší montáže. Před instalací a použitím si prosím pečlivě přečtěte tento průvodce.

Obecné bezpečnostní pokyny

- Ujistěte se, že je montáž kompatibilní s vaším dalekohledem a střelnou zbraní před instalací.
- Vždy manipulujte se střelnými zbraněmi opatrně a dodržujte všechny bezpečnostní protokoly.
- Uchovávejte montáž a všechny související komponenty mimo dosah dětí a neoprávněných uživatelů.
- Pravidelně kontrolujte montáž na známky opotřebení nebo poškození.
- Nahlaste jakékoli nebezpečné podmínky nebo incidenty příslušným úřadům.
- Sledujte informace o odvoláních produktů a bezpečnostních aktualizacích prostřednictvím platformy EU Safety Gate.

Specifické bezpečnostní opatření pro použití

- Používejte montáž pouze podle určení. Neměňte ji ani neprovádějte žádné úpravy.
- Ujistěte se, že jsou všechny šrouby a upevňovací prvky utaženy podle doporučených momentových specifikací.
- Vyhnete se používání montáže v extrémních podmínkách, které by mohly ohrozit její integritu.
- Nepřekračujte hmotnostní limit stanovený výrobcem.
- Vždy zkontrolujte stabilitu vašeho nastavení před použitím, abyste předešli nehodám.

Pokyny pro instalaci a používání

1. Příprava

- Shromážděte všechny potřebné nástroje: 1/2" taktickou matici a momentový klíč.
- Ujistěte se, že je vaše zbraň vybitá a směřuje bezpečným směrem.

2. Kroky instalace

- Umístěte montáž na požadované místo na liště zbraně.
- Upravte dalekohled v montáži, abyste zajistili správné uvolnění oka.
- Zajistěte montáž pomocí poskytnutých šroubů ve stylu Torx #8.
- Utažte šrouby na 65 in/lb. momentu pro bezpečné uchycení.
- Zkontrolujte, že jsou všechny komponenty bezpečně upevněny před použitím.

3. Pokyny pro používání

- Vždy se ujistěte, že je váš optický přístroj správně namontován a nastaven před výstřelem.
- Pravidelně kontrolujte montáž na stabilitu a utažení, zejména po intenzivním používání.
- Pokud si všimnete jakýchkoli známek poškození nebo nestability, okamžitě přestaňte používat a poraďte se s odborníkem.

Pokyny k likvidaci

- Likvidujte montáž v souladu s místními předpisy.
- Ujistěte se, že jakékoli elektronické komponenty, pokud jsou použity, jsou likvidovány na určeném zařízení pro elektronický odpad.
- Nemontujte montáž do běžného domácího odpadu.

Kontakt pro další podporu

Pokud máte jakékoli dotazy nebo obavy ohledně montáže XSKEL, prosím, obraťte se na webové stránky výrobce nebo zákaznický servis pro pomoc.

Dodržováním těchto pokynů můžete zajistit bezpečné a efektivní používání vaší montáže XSKEL. Děkujeme za vaši pozornost k bezpečnosti.