

X-SKEL MOUNTS - WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes ½" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH
- Manufacturer: WARNE MFG. COMPANY
- Product no.: 947000387
- Mfr. No.: XSKEL34DE
- Finish: Dark Earth
- Scope Tube Diameter: 34mm
- Style: Competition,3-Gun
- Delivery weight: 0.227kg
- UPC: 656813104925

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, DARK EARTH Safety Instruction Guide](#)
- [Český: XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, DARK EARTH Bezpečnostní pokyny](#)

XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH Safety Instruction Guide

Introduction

Thank you for choosing the XSKEL Mount from Warne MFG. Company. This guide provides essential safety instructions to ensure the proper and safe use of your mount. Please read this guide carefully before installation and usage.

General Safety Guidelines

- Ensure the mount is compatible with your optic and firearm before installation.
- Keep the mount and all accessories out of reach of children and vulnerable individuals.
- Regularly inspect the mount for signs of wear or damage.
- Follow all local laws and regulations regarding firearm accessories.
- Report any unsafe products or incidents to the relevant authorities.

Specific Safety Precautions for Use

- Do not exceed the recommended torque of 65 in/lb when attaching the mount.
- Ensure that the mount is securely fastened before use to prevent accidents.
- Avoid using the mount in extreme weather conditions without prior testing.
- Do not modify the mount or use it for purposes other than intended.
- If you experience any issues with the mount, discontinue use immediately and seek assistance.

Instructions for Installation and Usage

1. Preparation

- Gather all necessary tools, including a ½" hex nut driver and #8 Torx style fasteners.
- Ensure you have a clean and welllit workspace.

2. Installation Steps

- Align the mount with the optic and firearm.
- Use the ½" tactical nut to secure the mount in place.
- Tighten the fasteners to the recommended torque of 65 in/lb.
- Doublecheck all connections to ensure they are secure.

3. Usage

- Adjust your optic to the desired height and position for optimal eye relief.
- Regularly check the mount during use to ensure it remains secure.
- If you notice any movement or instability, stop using the mount immediately.

Disposal Instructions

- Dispose of the mount and packaging materials in accordance with local regulations.
- Do not dispose of electronics or hazardous materials in regular household waste.
- Consider recycling materials where possible.

Contact Information for Further Support

For any inquiries regarding safety or product usage, please refer to the manufacturer's contact information provided with the product packaging or on the official website.

By following these guidelines, you can ensure the safe and effective use of your XSKEL Mount. Thank you for your attention to safety, and enjoy your experience with our product.

XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH

Bezpečnostní pokyny

Úvod

Děkujeme, že jste si vybrali montáž XSKEL od společnosti Warne MFG. Tento průvodce poskytuje důležité bezpečnostní pokyny, které zajistí správné a bezpečné používání vaší montáže. Před instalací a používáním si prosím důkladně přečtěte tento průvodce.

Obecné bezpečnostní pokyny

- Ujistěte se, že je montáž kompatibilní s vaším optickým přístrojem a zbraní před instalací.
- Uchovávejte montáž a všechny příslušenství mimo dosah dětí a zranitelných osob.
- Pravidelně kontrolujte montáž na známky opotřebení nebo poškození.
- Dodržujte všechny místní zákony a předpisy týkající se příslušenství k palným zbraním.
- Nahlaste jakékoli nebezpečné produkty nebo incidenty příslušným úřadům.

Specifické bezpečnostní opatření pro používání

- Nepřekračujte doporučený točivý moment 65 in/lb při upevňování montáže.
- Ujistěte se, že je montáž bezpečně upevněna před použitím, aby se předešlo nehodám.
- Vyvarujte se používání montáže za extrémních povětrnostních podmínek bez předchozího testování.
- Nemodifikujte montáž ani ji nepoužívejte k jiným účelům, než k jakým je určena.
- Pokud zaznamenáte jakékoli problémy s montáží, okamžitě přestaňte používat a vyhledejte pomoc.

Pokyny pro instalaci a používání

1. Příprava

- Shromážděte všechny potřebné nástroje, včetně ½" hex matice a šroubů ve stylu Torx #8.
- Ujistěte se, že máte čisté a dobře osvětlené pracovní místo.

2. Kroky instalace

- Zarovnejte montáž s optickým přístrojem a zbraní.
- Použijte ½" taktickou matici k zajištění montáže na místě.
- Utáhněte šrouby na doporučený točivý moment 65 in/lb.
- Důkladně zkontrolujte všechna spojení, abyste se ujistili, že jsou bezpečná.

3. Používání

- Nastavte svůj optický přístroj do požadované výšky a polohy pro optimální uvolnění oka.
- Pravidelně kontrolujte montáž během používání, aby se zajistilo, že zůstává bezpečná.
- Pokud zaznamenáte jakýkoli pohyb nebo nestabilitu, okamžitě přestaňte montáž používat.

Pokyny pro likvidaci

- Zlikvidujte montáž a obalové materiály v souladu s místními předpisy.
- Nevyhazujte elektroniku nebo nebezpečné materiály do běžného domácího odpadu.
- Zvažte recyklaci materiálů, kde je to možné.

Kontaktní informace pro další podporu

Pro jakékoli dotazy ohledně bezpečnosti nebo používání produktu se prosím obraťte na kontaktní informace výrobce uvedené na obalu produktu nebo na oficiálních webových stránkách.

Dodržováním těchto pokynů můžete zajistit bezpečné a efektivní používání vaší montáže XSKEL. Děkujeme za vaši pozornost k bezpečnosti a přejeme vám příjemné zkušenosti s naším produktem.