

X-SKEL MOUNTS - WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, RED

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes ½" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, RED
- Manufacturer: WARNE MFG. COMPANY
- Product no.: 947000388
- Mfr. No.: XSKEL34R
- Elevation: -
- Finish: Red
- Height: -
- Scope Tube Diameter: 34mm
- Style: Competition,3-Gun
- Delivery weight: 0.259kg
- UPC: 656813104949

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, RED](#)
- [Český: XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, RED](#)

XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, RED

Consumer Safety Instruction Guide

Introduction

Thank you for choosing the XSKEL Mounts by Warne MFG. Company. This guide provides essential safety instructions, installation guidelines, and disposal information to ensure safe and effective use of your product. Please read this guide carefully before using the mount.

General Safety Guidelines

- **Product Safety:** Ensure proper handling and usage of the XSKEL Mount to avoid accidents. This product is designed for use with optical sights and should not be used for any other purpose.
- **Enhanced Recalls:** Stay informed about any product recalls. You can check for updates on the EU's Safety Gate platform.
- **Online Shopping:** If purchased online, ensure that the seller complies with safety requirements.
- **Special Consumer Focus:** Keep this product out of reach of children to avoid any potential hazards.
- **EU Contact Point:** For any safety inquiries, please refer to the manufacturer's contact information provided in the product packaging.
- **Rapid Alerts:** Be aware of any safety alerts related to this product through the Safety Gate system.

Specific Safety Precautions for Use

- **Weight Limit:** Ensure that the mount is compatible with your optical sight's weight specifications. Exceeding weight limits may compromise safety.
- **Secure Attachment:** Always use the recommended torque of 65 in/lb. for the tactical nut attachment to prevent loosening during use.
- **Inspection:** Regularly inspect the mount for any signs of wear or damage. Replace it immediately if any issues are detected.
- **Proper Eye Relief:** Ensure your optic is positioned correctly for eye relief to avoid eye strain or injury.
- **Avoid Modifications:** Do not alter or modify the mount in any way, as this may affect its safety and performance.

Instructions for Installation and Usage

1. Installation:

- Ensure you have all necessary tools, including a ½" hex nut driver and #8 Torx style fasteners.
- Place the mount on the designated rail of your firearm, ensuring it is aligned correctly.
- Secure the mount using the #8 Torx fasteners and the tactical nut. Tighten to the recommended torque of 65 in/lb.
- Doublecheck that the mount is firmly attached and does not wobble.

2. Usage:

- Once installed, mount your optical sight according to the manufacturer's instructions for the sight.
- Adjust the position of your optic to ensure it is at the ideal height and provides proper eye relief.
- Test the stability of the mount and optic before using the firearm.

Disposal Instructions

- Dispose of the product in accordance with local regulations.
- Do not dispose of the mount in household waste.

- Contact local waste management services for proper disposal methods of metal and aluminum components.

Contact Information for Further Support

For further support or inquiries regarding the XSKEL Mount, please refer to the manufacturer's contact details provided in the product packaging.

Thank you for prioritizing safety while using the XSKEL Mounts. Your adherence to these guidelines will help ensure a safe and enjoyable experience.

XSKEL MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, RED

Příručka pro bezpečnostní pokyny pro spotřebitele

Úvod

Děkujeme, že jste si vybrali montáž XSKEL od společnosti Warne MFG. Tato příručka poskytuje nezbytné bezpečnostní pokyny, pokyny k instalaci a informace o likvidaci, aby se zajistilo bezpečné a efektivní používání vašeho produktu. Před použitím montáže si tuto příručku pečlivě přečtěte.

Obecné bezpečnostní pokyny

- **Bezpečnost produktu:** Zajistěte správné zacházení a používání montáže XSKEL, abyste předešli nehodám. Tento produkt je navržen pro použití s optickými zaměřovači a neměl by být používán k jiným účelům.
- **Vylepšené stažení:** Zůstaňte informováni o jakýchkoli staženích produktu. Můžete zkontrolovat aktualizace na platformě EU Safety Gate.
- **Online nakupování:** Pokud jste zakoupili online, ujistěte se, že prodejce splňuje bezpečnostní požadavky.
- **Zvláštní zaměření na spotřebitele:** Uchovávejte tento produkt mimo dosah dětí, abyste předešli jakýmkoli potenciálním nebezpečím.
- **EU kontaktní místo:** Pro jakékoli dotazy týkající se bezpečnosti se prosím obraťte na kontaktní informace výrobce uvedené na obalu produktu.
- **Rychlé upozornění:** Buďte si vědomi jakýchkoli bezpečnostních upozornění týkajících se tohoto produktu prostřednictvím systému Safety Gate.

Specifické bezpečnostní opatření pro použití

- **Hmotnostní limit:** Ujistěte se, že montáž je kompatibilní s hmotnostními specifikacemi vašeho optického zaměřovače. Překročení hmotnostních limitů může ohrozit bezpečnost.
- **Bezpečné připevnění:** Vždy používejte doporučený točivý moment 65 in/lb pro upevnění taktického matice, abyste zabránili uvolnění během používání.
- **Inspekce:** Pravidelně kontrolujte montáž na jakékoli známky opotřebení nebo poškození. Ihned ji vyměňte, pokud zjistíte jakékoli problémy.
- **Správné uvolnění oka:** Ujistěte se, že je váš optický přístroj umístěn správně pro uvolnění oka, abyste předešli namáhání očí nebo zranění.
- **Vyvarujte se úprav:** Neměňte ani neupravujte montáž žádným způsobem, protože to může ovlivnit její bezpečnost a výkon.

Pokyny k instalaci a používání

1. Instalace:

- Ujistěte se, že máte všechny potřebné nástroje, včetně ½" hex matice a šroubů ve stylu Torx #8.
- Umístěte montáž na určenou lištu vašeho střelného zařízení a ujistěte se, že je správně zarovnaná.
- Upevněte montáž pomocí šroubů Torx #8 a taktického matice. Dotáhněte na doporučený točivý moment 65 in/lb.
- Zkontrolujte, zda je montáž pevně připevněna a nehýbe se.

2. Používání:

- Po instalaci připevněte svůj optický zaměřovač podle pokynů výrobce zaměřovače.
- Upravte polohu optiky tak, aby byla ve správné výšce a poskytovala správné uvolnění oka.

- Otestujte stabilitu montáže a optiky před použitím střelného zařízení.

Pokyny k likvidaci

- Likvidujte produkt v souladu s místními předpisy.
- Nevyhazujte montáž do domácího odpadu.
- Kontaktujte místní služby pro správu odpadu pro správné metody likvidace kovových a hliníkových komponentů.

Kontaktní informace pro další podporu

Pro další podporu nebo dotazy týkající se montáže XSKEL se prosím obraťte na kontaktní údaje výrobce uvedené na obalu produktu.

Děkujeme, že dbáte na bezpečnost při používání montáží XSKEL. Vaše dodržování těchto pokynů pomůže zajistit bezpečný a příjemný zážitek.